
Release Notes

Freescale eTPU(2) Development Suite v10.0 Release Notes for Patch 1.0

TABLE OF CONTENTS

1	<i>Known issues and Workarounds</i>	1
2	<i>Changes included in the Service Pack</i>	1
2.1	<i>Simulator changes</i>	1
2.2	<i>Compiler changes</i>	2
2.3	<i>ETPU visualization plugin features</i>	2

1 Known issues and Workarounds

Issue ID	Description
MTWX46525	<p>Issue: Switch between multiple projects in the same workspace might result in unpredictable behavior.</p> <p>Workaround: Debug one project at a time</p>
MTWX46628	<p>Issue: Trace information file is generated in D:\</p> <p>Workaround: Make sure that the workspace directory is on the same drive as the installation directory.</p>

2 Changes included in the Service Pack

2.1 Simulator changes

- Improved vector file support
- Improved TCRCLK scripting support
- Improved and fixed UDCM scenarios
- Fix for MTWX46655 – in some cases write watchpoints do not work

- Improved AM support
- Corrected sm_st_e unfiltered input

2.2 Compiler changes

- Upgraded to 1.4.2 version, see ETPU_10\Release_Notes\Compiler_Notes\FET Release Notes.txt for details
- Updated default LCF file

2.3 ETPU visualization plugin features

- Fix for MTWX45855
- Fix for MTWX46637

2.4 Other changes

- Updated stationary to the mnemonic change “ldch” instead of “ldm”