

Mask Set Errata for Mask 1N53H

Introduction

This report applies to mask 1N53H for these products:

- S08RN60

Errata ID	Errata Title
6657	ADC: ADC FIFO not working when the bus clock is slower than ADC clock divided by 2
5264	DBG: Comparator C with TAG type can not generate breakpoint when setting breakpoint at the address other than instruction opcode address

e6657: ADC: ADC FIFO not working when the bus clock is slower than ADC clock divided by 2

Errata type: Errata

Description: When the ADC FIFO mode is enabled, the FIFO can not get correct result if the bus clock is slower than ADC conversion clock divided by 2.

Workaround: Configure the bus clock to be faster than the ADC conversion clock (ADCK) divided by 2 if the ADC FIFO is used.

e5264: DBG: Comparator C with TAG type can not generate breakpoint when setting breakpoint at the address other than instruction opcode address

Errata type: Errata

Description: When setting breakpoint at the address other than instruction opcode address, the comparator C with TAG type can not generate breakpoint. This issue does not affect code execution.

Workaround: If such tag breakpoint at the address other than instruction opcode address is required, use comparator A and/or B tag breakpoint.



How to Reach Us:

Home Page:

freescale.com

Web Support:

freescale.com/support

Information in this document is provided solely to enable system and software implementers to use Freescale products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

Freescale reserves the right to make changes without further notice to any products herein. Freescale makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. Freescale does not convey any license under its patent rights nor the rights of others. Freescale sells products pursuant to standard terms and conditions of sale, which can be found at the following address: freescale.com/SalesTermsandConditions.

Freescale, the Freescale logo, AltiVec, C-5, CodeTest, CodeWarrior, ColdFire, ColdFire+, C-Ware, Energy Efficient Solutions logo, Kinetis, mobileGT, PowerQUICC, Processor Expert, QorIQ, Qorivva, StarCore, Symphony, and VortiQa are trademarks of Freescale Semiconductor, Inc., Reg. U.S. Pat. & Tm. Off. Airfast, BeeKit, BeeStack, CoreNet, Flexis, Layerscape, MagniV, MXC, Platform in a Package, QorIQ Qonverge, QUICC Engine, Ready Play, SafeAssure, SafeAssure logo, SMARTMOS, Tower, TurboLink, Vybrid, and Xtrinsic are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© 2014 Freescale Semiconductor, Inc.

